Certificate No: LR26240391AS
Issue Date: 22/05/2026
Expiry Date: 05/07/2029

Lloyd's Register Approved Service Supplier

Supplier Marland Boat Service Limited

Address Rm. 101, 1/F, Property 2, 108, No. 268 Maogang Road, Huangpu District, Guangzhou, Guangdong, 510799, China

Contact Details Email: Sherman@marland.com.hk

Contact Number Tel: +86 020-82360236

The above company having been assessed hereby receives approval in accordance with the requirements of Lloyd's Register Procedures for Approval of Service Suppliers as Supplier from the address(es) listed above for the provision of

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
1.Fassmer Service GmbH & Co. KG Model/Type: -Davit launched totally enclosed lifeboat: GMR 5.9/6.5/7.4/8.3, TGMR 5.9/6.5/7.4/8.3, CLR-C 5.9/6.4/6.8/7.2/7.6/8.1/8.5, CLR-T 5.9/6.4/6.8/7.2/7.6/8.1/8.5, CL-C8.9/9.4/9.8/10.2/10.7/11.1/11.5/11.9/12.4/12.8/13.2, CLT8.9/ 9.4/9.8/10.2/10.7/11.1/11.5/11.9/12.4/12.8/13.2, CLX (R)8.5/10.0/11.7/12.8; -Freefall Lifeboat CFL 4.9/-T4.9, GAR 6.0/-T6.0/6.8/-T6.8/6.7/-T6.7/7.4/-T7.4/8.1/-T8.1/7.7/-T7.7/8.5/-T8.5, CFLC66/72/77/83, CFL-T66/72/77/83; -Partially enclosed Lifeboats & rescue boat: CL-P 5.9/6.4/6.8/7.2/7.6/8.1/8.5/8.9/9.4/9.8/10.2/10.7/11.1/ 11.5/11.9/12.4/12.8/13.2, SEL8.15/8.8/9.6/10.5/10.55/11.8/12.5/15.75/, SEL-R 8.15, SEL-T 10.75, TL Limo 1100, SEL-T 11.0/11.7/12.3/14.0/14.7/15.75, PLL 1099, PLT-EVO 170, SEL-RT 7.7/7.5/8.5; SEL11.0(-T); SEL-R 7.4/8.5; SEL 11.0(-T); SEL-R 7.4/8.5; -NAVY RHB: SFB 10.1; - Rescue boat: RR 4.2/4.2-M/4.5ID; RIR 625ID; FR(I) R6.1/6.1ID, FRR 6.2ID/6.5ID-SF/6.6ID/7.0ID-SF/7.0, FRIR6.25; -Release Mechanism: FFRU6.6; FOH 27/30/70; Duplex25E2/2.5E/50E2/5.0E/60E2/6.6E/10E/140E2/ 14E/17E/180E2/230E2/23E；2.5T/5.0T/10T/14T/17T/23T; -Launching appliances: davit/crane/winch

Downloaded Copy

Room 02-05, 48F, Raffles City Shanghai Office Tower, No.268 Xi Zang Middle Road, Huangpu District, Shanghai, 200001, China

Zhi Qiang Li

Lead Surveyor to Lloyd's Register
Classification Society (China) Co., Ltd.
A member of the Lloyd's Register group

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Lloyd's Register Approved Service Supplier

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
FHD 80/100/120/130/150/170/172/280/450; FHDY 100; FFH 45/65; FPD 55/60/100/80/120/150/170/FFD D60; FFH 49/50/60/66/70/72/75/77/80/83/85/90; FLR49/66/8005/8006/8007; FMPD 100/130/150/160; FOD 100/120/130/150/170/190/40R/50/55/80/LBC 300/SAR40/-R22/-R23/-R25/-R40/TC450; FOSV 71; FSAH22; FSAH 28/32, FSAR 12/3.5,FSAR 14/2.9, FSAR 14/3.5, FSARR 14/3.5, FSAR 21/4.0, FSAR 21/4.5, FSARR 21/3.8, FSARR 21/4.0, FSARR 21/4.3,FSAR 22/4.5, FSARR 22/4.0, FSAR 28, FSAR 40; PRHE30; DEW 40/85/2000; DEW 8, FWD 40RB, DEW 150; FFWH; 2.Fassmer-Marland Ltd. (ex. Hai Hong Boat Making Co., Ltd. (Guangzhou) Model/Type: DRAGON 26C/26T/32C/32T/38C/38T; DRAGON 26C-M/26T-M/32C-M/32T-M/38C-M/38T-M; GMR6.5/ -T6.5/7.4/-T7.4, HH57C/57T/65C/65T/70C/70T; CLR-C5.9/T5.9; GAR6.7/-T6.7/7.4/-T7.4; CFL-C49(E)/T49(E)/C66(E)/T66(E)/C72(E)/T72(E)/ C77(E)/T77(E)/C83(E)/T83(E); RR4.2/4.2-M, RRH4.2, RR4.2ID; FRR6.1ID/6.2ID; Duplex 2.5/2.5E/25E2/5.0/5.0E/50E2, HH43, FFRU6.6/FM53, SINGLE TYPE: 5.1T FPD-D60/D68/DH68, SRH70; FFH49/49D/66/66D/72/77/83; FLR49/66/72; FSAR14/3.5HS, 4.0/3.5HS, 21/4.0HS, FSAR 25; FSARR 14/3.5HS, 21/4.0HS, 22/4.0HS, FMAH 22KN; DEW 15-24/15-35/15-44,D52L/R,DW34S/Z; MW 45/45C, MW50/50C; FFWH35-16, FFWH50-18; DEW 150/450, RZ25; 3. HLB Co., Ltd. (Hyundai Lifeboat Company Ltd.) & BADA Heavy Industries Co., Ltd. Types of products manufactured by HLB (ex, Hyundai Lifeboats) Co., Ltd Lifeboats & Rescue: Series of HD, HT, HDL, HLB,HDF, HDFL, HDFN, HDR & HDFR; Release mechanism type: Series of THP, Titan, TALON & TALON II; Types of products manufactured by BADA Heavy Industries (ex, D.R.M) Co., Ltd. Davit: Series of DRM,DRBD,BDH,BDTD,BDHP,BDTW,BDRW,BDM,BFOD,HDL,BHR FF,HDFL,HDF,BDF,BDFD,BDR,BDH,BDA,BDFA,BDL,BDR,BLR&BHI Winch: Series of DRM,DRBW,HLDF,BAW,BDF,BDFD,HDFL,HDF,BHI,BLR,BLW,BMW,BRW,BWL,BWR&FHW Release Mechanism: Series of BDR, BHA & BHR; 4. IKNOW Machinery Co., Ltd (ex. Tsuji Heavy Industries Co., Ltd.) Model/Type: Davit: H, T, TC;

Downloaded Copy

Room 02-05, 48F, Raffles City Shanghai Office Tower, No.268 Xi Zang Middle Road, Huangpu District, Shanghai, 200001, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Lloyd's Register Approved Service Supplier

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
Winch: EB, TC, OAP; 5.Japan Marine United Corporation (IHI Craft, IHI AMTEC, IHI Marine United Inc.) Model/Type: GF80B, GF80C, GF80E, GF80F, GF80G, GF80H, GTR57(C,F), GTR57JY(C,F), GTC60C, GTC65(C,F), GTC70(C,F), GTC75(C,F), GT65F, GT70F, GT75F Others(JY series of Jiangsu Jiaoyan with JMU nameplate with JG shop inspection approval certificate); MU-FN-5.8J, MU-FF-5.8J, MU-FN-6.8J, MU-FF-6.8J (S65A/S73A/S75A/80A/G73B/G73C/G75A/G80A); MUL52 (Winch: MUW42R/MUW42L), MUF55J, MUF75J; MU-GJ4.5J, MUR21J; 6.Jiangsu Jiaoyan Marine Equipment Co., Ltd. (Formerly: Jiangyin Xinjiang F.R.P. Co., Ltd.) Model/Type: JY-FN-4.9, JY-FF-4.9, JY-FN-5.8, JY-FF-5.8, JYM-FN-6.65, JYM-FF-6.65, JY-FN-6.8, JY-FF-6.8, JY-FN-7.5, JYFF-7.5, JY-FN-8.5, JY-FF-8.5,JY-FN9.5,JY-FF-9.5, GJ4.2, GJ4.25, GJ4.5, GJ5.0, GJ5.25, GJ6.0B-1, GJ6.10, GJ7.50/GJ8.0Q-2, GJ8.5Q-2; JY-QFP/N-5.0, JY-QFP/N-5.25,,JY-QFP/N-5.6, JY-QFP/N-6.0A, JY-QFP/N-6.50, JY-QFP/N-7.0, JY-QFP/N-7.5, JY-QFP/N-7.50A, JY-QFP/N-8.00, JY-QFP/N-8.50, JY-QFP/N-8.50X, JY-QFP/N-9.35, JY-QFP/N-10.90/10.90A; JX AND JXN Series JYL52/JYL55/JYL65/JYL68/JYL85/JYL105/JTL135; JYF55/JYF75/JYF-75-A/JYF-75-B/ JYF90; JYP65/ JYP85/ JYP105/JYP135,JYP170/JYW100L JYR21/JYR21S-A/JYRC21/JYR14/JYRH14/JYRH21/JYR23/JYR26/JYR30; FW45/ JYW42/ JYW50/ JYW70 /JYW100 /JYWP70/ JYWP100/ JYWP135 /JYW35 /JYRZ21; 7.Mansei Inc.(Mansei Industry Co., Ltd.)Miura Machine Co., Ltd.(Miura Vider Co., Ltd.) Types of products manufactured by MANSEI INC. Davits: Series of EBD-, EM-, ABD-, AH-, AT-, and AV-, Series of EH-, ET-, EV-, M- and CM-, Series of D-FH., DE-FH., MFE- and MFH-, Series of SR-, SRE-, R-, S-, RDand EHR- Winches: Series of EBW-, ABW- and AW-, Series of EW-, MW-, and CMW-, Series of 06., and FW-, Series of SW-, RMW-, MLW-, and ERW-, Release Hooks: Series of RHTypes of products manufactured by MIURA MACHINE CO., LTD. Davit: Series of SP, MVD, GRA and SAR; Winch: Series of BH, BE and BA;

Downloaded Copy

Room 02-05, 48F, Raffles City Shanghai Office Tower, No.268 Xi Zang Middle Road, Huangpu District, Shanghai, 200001, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Lloyd's Register Approved Service Supplier

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
8.Nishi-F Co., Ltd.(ex. Nishi Nippon F.R.P. Shipbuilding Co., Ltd.)(ex. Ishihara Dockyard) Model/Type: Totally & Partially Enclosed, Free-Fall, Fire Protected, and Open Type G Series :G-48ATR, G54ATR, G-63ATR, G-65BTR, G-73DTR, G-80CTR, G-90BTR, G-54AFR, G-63AFR, G-65BFR, G-73DFR, G-80CFR, G-73C ML Series :EML-18, CML-19, CML-20, CML-21, CML-22, CML-23, CML-25, CML-27, PML-22, PML-35, CML-19S, CML-20AS, CML-21S, CML-22A, CML-23S, CML-25AS, CML-27AS, DML-73, DML-73S F Series: FF-65, FF-65S, FF-72, FF-72S, F-43, NF-73A, NF-75 IHM Series: IHM-12, IHM-12B, IHM-13 NS Series: NS-2.5, NS-3, NS-5 SR Series: SR-1, SR-3 (SRS-37), SR-4, SR-6 FF Series: FF-H6T. FF-H7T 9. Oriental Precision & Engineering Co., Ltd. Model/Type: Series of HGD, HGK, SHS, RTD, DHA, DMA, STS, Series of BWE, SWE, WL; Series of FD, WL; Series of RD, RDW; 10.Sekigahara Seisakusho Ltd. Model/Type: SH, SFB, SHS, STS, SSS SFS, SFA, SFB, SFC, SFD SJS, SJR 11.Shigi Shipbuilding Co., Ltd. Model/Type: Series of SZ, FEL, VOX, GARS, Open Type and Release Gear manufactured by Shigi Shipbuilding Co., Ltd. 12.Tsuneishi Facilities &Craft Co., Ltd.(Sanyo Works Co., Ltd.)(Kamara Ringyo Co., Ltd.)(Tsuneishi Forestry Construction Co., Ltd.)(Tsuneishi Holdings Corporation Tsuneishi Forestry Construction Company) Model/Type: 7.32M Open Type, KL-6.5TE, KL-6.5FP, TL-6.5TE, TL-6.5FP, TL-5.7TE Fixed Type Hook: 43GS-1(A),43GS-1(B),43GS-1(C),43GS-1(D) 13.Wuxi Hai Hong Boat Making Co., Ltd Model/Type: HH50C / HH50T, HH53C / HH53T(QFP(H)5.3), HH57C / HH57T, HH65C / HH65T (QFP(H)6.5/QFN(H)6.5), HH65CS /HH65TS(QFP6.5/QFN6.5),

Downloaded Copy

Room 02-05, 48F, Raffles City Shanghai Office Tower, No.268 Xi Zang Middle Road, Huangpu District, Shanghai, 200001, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Lloyd's Register Approved Service Supplier

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
HH70C / HH70T(QFP7.0/QFN7.0), HH75CS / HH75TS(QFP7.5/QFN7.5),HH75C (QFP(H)7.5), HH80CS / HH80TS (QFP8.0/QFN8.0), HH85C / HH85T, HH85CS / HH85TS (QFP8.5/QFN8.5), HH59FC / HH59FF, HH76FC / HH76FF, GJ4.5B / GJ4.5B1, GJ618A / GJ618B, HH76 /HH43/HH30/HH20 14.Wuxi Dongwu Marine Equipment Co., Ltd. 18KN, 25KN, 40KN, 50KN, 60KN, 85KN, 110KN, T2.5, SK50 25KN Sliding track, 30KN Sling track F55, F70, NPT100F 21KN (Manual), 21KN (Electrical), 21KN (Electrical / Hydraulic), 25KN (Electrical / Hydraulic), 35KN (Electrical / Hydraulic), D52R/D52L, DZY/Z21, DS*ZY25, DZ*ZY25, DS*ZY40, DZ*ZY40, D50S/Z, DS*ZY63, DZ*ZY63, D63S/Z, 80KnA30, H35, LE68 15.Qingdao Beihai Shipbuilding Heavy Industry Co., Ltd. Remark: case by case approval letter is required by maker for following model/type: BH-5/BH-5A/BH-5S/BH-5SA/BH-E500/BH-E585/BH-6/BH-6A/BH-6S/BH-E670/BH-7A/BH-7B/BH-8 BHF6.0/BH-F7.0A/BH-F7.8/BH-F8.1/BH-F5.8/BH-F6.8/BH-F660/BH-F670/BH-F750/BH-900A BH-R4/BH-R4S/BH-R4SA/BH-R5S BD-PV50, BD-PV60, BD-PV60S, BD-PV85, BD-PV125 BD-FF55, BD-FF55A, BD-FF55R, BD-FF80, BD-FF80A, BD-FF80R, BD-FF80B, BD-FF65, BD-FF66, BD-FF67, BD-FF85, BD-SA14, BD-SA14A, BD-SA14B, BD-SA21, BD-SA21A, BD-SA23, BD-SA30, BD-SA30A, BD-SA33, BD-SH23 BW-H(L/R)31, 50, 63, 75, L(L/R)75, 125, SC14, 21, 30 YSB series BG-3, BG-3R, BG-3L, BG-7, BH-HOOK3, BH-HOOK5, BH-FS5, BH-FS7, BG-3F, BG-3.5F, BG-4F, BG-4.5F, BG-4.5FL, BG-5F, BG-6F, BG-2R, WUXI QINGSHENG 15,21,23,25,35KN HOOK 16.WUXI XINGSHENG GEAR CASE FACTORY Model/Type: 15KN(XS15), 21KN(XS21), 23KN(XS23), 25KN(XS25), 35KN(XS35); 17.WUXI MING ZI MACHINERY MANUFACTURING CO., LTD Model/Type: HK40, WHK40, WHK65, 15KN(150-T), 21-25KN(250-T), 31-37KN(370-T)

Downloaded Copy

Room 02-05, 48F, Raffles City Shanghai Office Tower, No.268 Xi Zang Middle Road, Huangpu District, Shanghai, 200001, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Certificate No: LR26240391AS
Issue Date: 22/05/2026
Expiry Date: 05/07/2029

Lloyd's Register Approved Service Supplier

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
18.DH Marine Equipment Co., Ltd. A Type Rescue Boat Davit: PR 30, PR 35, PRH 30, PRH 35 Life raft Davit: MSD23, MSD 33, LE40 Freefall Davit: FFH 55, FFH 75, FFH95 Single Arm Davit: HSD 15, HSD 23, HSD 30 Gravity luffing arm davit: LE 90， LE 120 Telescope Crane: HTD30 Hydraulic Gravity Luffing Davit: LPRH90, SRH70, SRH120, SRH180, SRH200, SRH220 , SRH260 Connecting Rod Type Davit: VLG200 Connecting Rod Type Davit: PL65 ,PL138, PL150, PL180, PL230 Winch Type: DW15, DW25, DW34, DW50, DW75, DW100, DW110, DW120, DW138, DW150, DW168, DW180. This Service Supplier has been approved to service the equipment in accordance with IMO Resolution MSC.402(96), as amended. Service engineers are to be provided with a valid Certificate, issued by this Approved Service Supplier, which defines their level of qualification and the scope of the certification (i.e. makes and types of equipment and specifically state which activities (e.g. annual thorough examination and operational tests; 5-year thorough examination, overhaul; overload operational tests; repairs) are covered by the certification). This Certificate should be made available when requested.

This approval is conditional upon the Supplier maintaining the documented scheme as audited by any member of the Lloyd's Register Group and hereby approved; and notifying Lloyd's Register in writing of any change to that scheme including any change in personnel, equipment or procedures. This certificate is issued to the Supplier and, subject to the Supplier complying with the necessary conditions, is valid to the date referred to above.

Downloaded Copy

Room 02-05, 48F, Raffles City Shanghai Office Tower, No.268 Xi Zang Middle Road, Huangpu District, Shanghai, 200001, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.