Certificate No: LR23308269AS
Issue Date: 08/06/2023
Expiry Date: 07/06/2026

Lloyd's Register Approved Service Supplier

Supplier UMS Uruguayan Marine Safety

Address Arturo Lezama 2228, Montevideo, 11800, Uruguay

Contact Details weserve@ums.com.uy
www.ums.com.uy

Contact Number +598 2 924 6025
+598 2 924 4938

The above company having been assessed hereby receives approval in accordance with the requirements of Lloyd's Register Procedures for Approval of Service Suppliers as Supplier from the address(es) listed above for the provision of

Inspections And Maintenance Of Fire-Extinguishing Equipment And Systems

Servicing Of Inflatable Liferafts, Inflatable Lifejackets, Hydrostatic Release Units, Marine Evacuation Systems
VIKING: - KF,DFF, DFK+,DKFS, MOR (Means of rescue) lifereafts: up to 39 persons -DKR/IBA/RDV liferafts without remote reléase sysem: up to 65 persons -UK,CL,UKL,UKSL,UKCL liferafts: all sizes -K,DK,DK+, DKS non-system liferafts: up to 50 persons RFD RFD Coastal, RFD Endura (´MKI´) DL, RFD Endura (´MKI´) TO, RFD Endura (´MKIII´) TO, RFD Endura (´MKIII´) DL, Seasava 4,

Downloaded Copy

Oscar Alvarez

Lead Surveyor - Buenos Aires to Lloyd's Register Central and South America Ltd
A member of the Lloyd's Register group

Torre Américas, Av. Américas 140, Piso 14 Int. 1405-1406, Fracc. Las Américas, Boca del Río, Veracruz, CP. 94298, Mexico

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Certificate No: LR23308269AS
Issue Date: 08/06/2023
Expiry Date: 07/06/2026

Lloyd's Register Approved Service Supplier

Servicing Of Inflatable Liferafts, Inflatable Lifejackets, Hydrostatic Release Units, Marine Evacuation Systems
Seasava plus (´MKI´), Seasava plus (´MKIV´), Seasava plus (´MKIII´), Surviva (´MKI´) DL, RFD Surviva (´MKI´) TO, Surviva MA, RFD Surviva (´MKII´), Surviva (´MKIII´) DL, Surviva (´MKIII´) TO, Surviva (´MKIV´) DL, Surviva (´MKIV´) TO. ZODIAC: Survitec Zodiac Coastal, Survitec Zodiac DL, Survitec Zodiac DL, Survitec Zodiac DL SR, Survitec Zodiac IBA reversible, Survitec Zodiac (´MKIV´) DL, Survitec Zodiac (´MKIV´) TO, Survitec Zodiac ORIL, Survitec Zodiac TO, Survitec Zodiac TO two years first service, Survitec Zodiac SR. DSB: LR05, LR05 L, LR86 L, LR86, LR07, LR07 L, LR97 L, LR97. CSM: RAFT-A-6(II)/10(II)/15(II)/ 16(II)/ 25(II) RAFT-D-6/8/10/15/ 16/ 20/ 25 SMRL-A-6/8/10/15/ 16/ 20/ 25(I) SMRL-D-12/ 16/ 20/ 25/32 RAFT-SR-6/8/10/15/ 16/ 20/ 25/50/55/65

Downloaded Copy

Torre Américas, Av. Américas 140, Piso 14 Int.
1405-1406, Fracc. Las Américas, Boca del Río,
Veracruz, CP. 94298, Mexico

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Lloyd's Register Approved Service Supplier

Servicing Of Inflatable Liferafts, Inflatable Lifejackets, Hydrostatic Release Units, Marine Evacuation Systems
RAFT-DSR-6/8/10/15/ 16/ 20/ 25/32/37 RAFT-R-6/15/25/30/50//65/66/66*2 Shangai youlong Rubber Products Co.Ltd.: KHA-6/8/10/12/15/ 16/ 20/ 25/30/35 KHZ-6/10/15/20/25/50/65/100/110/125/130. KHD-12/15/16/20/25/30/35. KHZD-25,37 KHK-6/10/25/30/50/65/100 KHY-4/6/8/10/12 KHYJ-4/6/8/10 KHY(SR)-4/6/8/10/12 INFLATABLE LIFE JACKETS: VIKING: SOLAS approved inflatable lifejackets

Inspections And Maintenance Of Self-Contained Breathing Apparatus
LALIZAS Breathing Devices (LALIZAS Emergency evacuation Breathing device''ESCAPE-15'') LALIZAS Breathing Devices (LALIZAS Self Contained Breathing Apparatus) JIANGSU HUAYAN EEBD EEBD TH10, TH15; SCBA RHZK6/30, RHZK5/30, RHZK6.8/30

Hydraulic Tests Of Low And High Pressure Cylinders

Service Of Immersion Suits, Thermal Protective Aids, And Chemical Protective Clothing
LALIZAS Immersion Suits Insulated.

Downloaded Copy

Torre Américas, Av. Américas 140, Piso 14 Int.
1405-1406, Fracc. Las Américas, Boca del Río,
Veracruz, CP. 94298, Mexico

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Certificate No: LR23308269AS
Issue Date: 08/06/2023
Expiry Date: 07/06/2026

Lloyd's Register Approved Service Supplier

Service Of Immersion Suits, Thermal Protective Aids, And Chemical Protective Clothing
LALIZAS Inflatable Lifejackets J IANGSU HUAYAN Immeersion suits HYF-2, HYF-N2, HYF-N

Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear
HLB, (Ex Hyundai Lifeboats Co., Ltd / BADAHI: SERIES: HD,HT,HDL,HLB,HDF,HDFL,HDFN,HDR &HDFR Release mechanism: Series of THP, Talon I & Talon II Davits and winches (BAD (ex D.R.M.)) Davit: Series of DRM,BDH,BDTB,BDHP,BDTW,BDRW,BDMand BFOD. Series of FF, HDFL, HDF, BDF, BDR, BDH,BDA, BDFA, BDL, BDR, BLR & BHI Winch Series of DRM,DRBW, BAW, BDF,BHI,BLR, BLW,BMW, BRW, BWL, BWR, &FHW. Release Mechanism series of BDR,BHA &BHR This Service Supplier has been approved to service the equipment in accordance with IMO Resolution MSC.402(96), as amended. Service engineers are to be provided with a valid Certificate, issued by this Approved Service Supplier, which defines their level of qualification and the scope of the certification (i.e. makes and types of equipment and specifically state which activities (e.g. annual thorough examination and operational tests; 5-year thorough examination, overhaul; overload operational tests; repairs) are covered by the certification). This Certificate should be made available when requested.

This approval is conditional upon the Supplier maintaining the documented scheme as audited by any member of the Lloyd's Register Group and hereby approved; and notifying Lloyd's Register in writing of any change to that scheme including any change in personnel, equipment or procedures. This certificate is issued to the Supplier and, subject to the Supplier complying with the necessary conditions, is valid to the date referred to above.

Downloaded Copy

Torre Américas, Av. Américas 140, Piso 14 Int.
1405-1406, Fracc. Las Américas, Boca del Río,
Veracruz, CP. 94298, Mexico

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.